






February 27, 2010 Earthquake Data  
Port Facilities and Damage  
Typical Container Berth Quay Construction  
Quay and Crane Seismic Design  
Other facilities

2 of 29













## San Antonio Port



Source: Wikipedia



9 Berths - 7 operating as of March 5  
6 Gantry cranes

6 of 29



## STI - San Antonio

3 Berths - 6 gantry cranes  
2 Gantry cranes damaged  
(not from earthquake)



Source: Google Earth

7 of 29



## STI Crane Damage



Photo Courtesy of MIT

8 of 29







## STI Gantry Trucks Derailed



10 of 29



## STI Yard Cargo Damage



11 of 29



## STI Quay & Yard Damage





12 of 29





## STI Quay & Yard Damage




13 of 29



## STI Quay & Yard Damage



14 of 29



## Puerto Panul Public Terminal



15 of 29





## San Vicente Terminal

3 Berths - none operating



Photo Courtesy of MIT/Berger ABAM

### Quay Damage

16 of 29





## San Vicente Terminal - Yard



Separation – up to 22 cm wide, 2.3 m deep

Photos Courtesy of Berger/ABAM

17 of 29






## TPSV - Valparaíso

8 berths - 6 operating  
5 gantry cranes - no damage



Source: Google Earth

18 of 29



## Quay Construction


### San Antonio and Valparaiso Container Berths

- Concrete deck
- Vertical steel piles at 5 - 6 m longitudinal spacing
- Moment resistant frame
- Built after 1985 earthquake


19 of 29



## Crane Seismic Design





50' Gage



100' Gage or Larger

20 of 29



## Crane Seismic Design


Historical




- 0.2 g uniform horizontal acceleration

Liftech Current Recommendation



- Elastic tipping
- Ductile yielding
- Isolation

21 of 29









## Ductile Yielding



23 of 29



## Seismic Isolation




Portal Beam


Isolation Hinge

Lower Leg

**Liftech Design**



**MHI Design**



**ZPMC Model**

24 of 29





## Santiago Airport



25 of 29



**Kobe 1995** Magnitude 6.9 - PGA = 0.5 g






Source: Liftech

**Haiti 2010** Magnitude 7.0 - PGA = 0.25g



Source: Flickr




26 of 29




## Summary- Major Ports

- Large magnitude earthquake
- Quay structures performed well
- Yard settlement at some terminals
- Gantry crane damage
  - Minor from earthquake
  - Significant collateral to two cranes

27 of 29





Thank You

This presentation will be available for download on our website:  
[www.liftech.net](http://www.liftech.net)

Additional information is available in our blog:  
[www.liftech.net/blog](http://www.liftech.net/blog)

28 of 29



Liftech Consultants Inc. file data:  
N:\Papers & Presentations\Working\2010\_TOC\_Asia\_AB\ChileEarthquake\TOC\_ChileEarthquake\_01\_djl.ppt

Copyright 2010 by Liftech Consultants Inc. All rights reserved.

This material may not be duplicated without the written consent of Liftech Consultants Inc., except in the form of excerpts or quotations for the purposes of review.

The information included in this presentation may not be altered, copied, or used for any other project without written authorization from Liftech Consultants Inc. Anyone making use of the information assumes all liability arising from such use.

*Quality Assurance Review:*

Author: Arun Bhimani  
Editor: Teresa Ferguson

29 of 29